

Barco Insights Management Suite

Availability matrix



	G50	G62	G100	I600	UDM	UDX	XDM	XDX
Projector & light source runtime	✓	✓	✓	✓	✓	✓	✓	✓
Ambient temperature & humidity information	✓	✓	✓	✓	✓	✓	✓	✓
AC voltage information	-	-	-	-	✓	✓	-	-
Take custom notes	✓	✓	✓	✓	✓	✓	✓	✓
Set FLEX ² brightness and resolution value	-	-	-	✓	✓	✓	-	-
Projector firmware version	✓	✓	✓	✓	✓	✓	✓	✓
Projector connection status	✓	✓	✓	✓	✓	✓	✓	✓
View current health issues	✓	✓	✓	✓	✓	✓	✓	✓
View IP address	-	-	-	✓	✓	✓	-	-
Cloud service manuals	-	-	-	✓	✓	✓	✓	✓
View and filter health notification history	✓	✓	✓	✓	✓	✓	✓	✓
Trigger & download diagnostics package	-	-	-	✓	✓	✓	-	-
Receive health notifications via e-mail	✓	✓	✓	✓	✓	✓	✓	✓
Access cloud data through API	✓	✓	✓	✓	✓	✓	✓	✓
Manage projector power schedule	-	-	-	✓	✓	✓	-	-
Manage IP address	-	-	-	✓	✓	✓	-	-

Check the projector manual to see feature availabilities.